NEW ENGLAND AERO SERVICES

AIRFRAME MAINTENANCE RECORD

Make	Model	Serial Number	Registration	Date
TL Ultralight	2000 Sting S4	18ST468	N336ST	7-1-2023
Tach Time:	542.6	**AF TT:**	542.6	**Hobbs:**

Performed an annual Condition inspection using a **TL-2000 Sting S4** checklist.

The following additional maintenance was performed:

1. Entire aircraft lubed, brake reservoir and battery serviced.

Tested ELT I/A/W FAR 91.207 (d). B.

All ADs checked for compliance through issue **2023-12**.

I certify that the above stated maintenance and/or inspection(s) was performed in accordance with the current FAR's, and the airframe or engine identified above was found to be in an airworthy condition and is approved for return to service with respect to the work performed. Details are located on file under Work Order No._____.

Signature: _____ **Name: Gerry Sykes. Certificate Number: A&P 3664796 IA**

AEROSPORT LLC SP# 3722442

N336ST. HOBBS. 615.1 A/C TT: 615.1 05//14/2024

REPLACED AIR FRAME BATTERY YUASA MF YT12A-BS 10.5 AH 175 (20HR) 175 (CCA)

Timothy Bonin

TIMOTHY BONIN

N336ST mn: Sting S4 s/n: 18ST468 Tach: 629 ACTT: 629 7/25/2024

Date

100hr ANNUAL Condition Inspection completed iaw Sting S4 inspection checklist. Checked all lights,stall warning horn. Installed new elt battery(pn: 11-06297). Ops checked Elt per FAR 91.207D. Elt battery expires 12/2030. Lubed aircraft and landing gear as required. Inspected and serviced tires/bearings, brakes & battery as required. Inspected wings, controls, cables & pulleys. Install new tire on L main wheel assembly. ADs checked thru issue 2024-14. All operational checks - satisfactory. All work performed iaw Sting S4 Service Manual and AC43.13-1b. I certify that this Aircraft has been inspected iaw an ANNUAL Condition Inspection and was determined to be in an Airworthy condition.

Brian M Rice AP3272916!A
Northampton Aeronautics, Inc. (7B2)

STELLAR Avionics Services, LLC Chester Airport Chester, CT 06412 FAA CRS YZSR344Y
LOG ID# 4122 10-September-2024 WO# 19462 REF# A19462
N336ST S/N 18 ST 468 Ultralight S R O TL 2000 Sting S4

Pg 1 / 1

1) Complied with FAR 91.413 Biennial Transponder Test/Inspection for Garmin GTX-45R Transponder S/N 4Y000681 in Accordance with FAR Part 43, Appendix F, and Found Airworthy.

The aircraft, airframe, aircraft engine, propeller, or appliance identified above, was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service for the work performed. Pertinant details of the repairs are on file at this Repair Station under the Work Order listed above.

----------END----------

YZSR344Y 9/10/24
Date

10

Date	Number of flight hours	Description of maintenance	AIRCRAFT CONDITION		Notes	Signature
			BEFORE maintenance	AFTER maintenance		

N336ST Tach:689 ACTT:689 07-01-2025

100 hour annual condition inspection completed i/a/w Sting S4 checklist. Inspected ELT i/a/w FAR 91.207D. No discrepancies noted. Batteries expire 12-2030. Checked all lights, stall warning, battery and brakes. Inspected wings, controls, cables and pulleys. Lubricated aircraft as necessary. I certify that this aircraft has been inspected i/a/w the Manufacturers Maintenance and Procedures Manual and was found to be in a condition for safe operation.

Hillary M. Carlson AP3365016
Northampton Aeronautics, Inc.

AEROSPORT LLC 3722442

N336ST MOD. S4. S/N 18ST465. TACH. 715 ACTT 715 10/03/2025

INSTALLED NEW TIRE ON R MAIN GEAR ASSEMBLY.

TIMOTHY BONIN

Date 03/26/2026 N336ST TL-ULTRALIGHT S R O TL 2000 STING S4

Tach 734.6

DITION	Notes	Signature
FTER aintenance		

Airframe

Removed and replaced with Facet Cube 12 Volt Fuel Pump (Part# FAC-40135)
Replaced 2 fittings AN816-6-2D
Tested. Ops good. No leaks.

All work done in accordance with maintenance manual using 43.13 as a guide.

A&P James Caradonna 22581842

CARADONNA 3BO AVIATION

N336ST Tach:747 ACTT:746 07-01-2026

100 hour/annual condition inspection completed i/a/w Sting S4 checklist. Inspected ELT i/a/w FAR 91.207D. No discrepancies noted. Batteries expire 12-2030. Checked all lights, stall warning, battery and brakes. Inspected wings, controls, cables and pulleys. Lubricate aircraft as necessary. Replaced elevator trim cable with new in accordance with Sting S4 maintenance manual. Service bulletin ASB_A-2026-001R00 does not apply by engine serial number and gearbox part number and serial number. I certify that this aircraft has been inspected i/a/w the manufacturers maintenance and procedures manual and was found to be in a condition for safe operation.

Hillary M. Carlson AP3365016
Northampton Aeronautics, Inc.

AEROSPORT LLC 3722442

N336ST MOD. S4. S/N 18ST465. TACH. 759.6 ACTT 759.6 08/13/26

INSTALLED NEW BATTERY YUASA YT-12A-BS

Timothy Bonin

TIMOTHY BONIN

Signature

STELLAR Avionics Services, LLC Chester Airport Chester, CT 06412 FAA CRS YZSR344Y
LOG ID# 4402 24-August-2026 WO# 20404 REF# A20404
N336ST S/N 18 ST 468 Ultralight S R O TL 2000 Sting S4 Pg 1 / 1

1) Complied with FAR 91.413 Biennial Transponder Test/Inspection for Garmin GTX-45R Transponder S/N 4YC000681 in Accordance with FAR Part 43, Appendix F, and Found Airworthy.

2) Updated GTX-45R software from 2.54 tp 2.90.

The aircraft, airframe, aircraft engine, propeller, or appliance identified above, was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service for the work performed. Pertinant details of the repairs are on file at this Repair Station under the Work Order listed above.

----------END----------

24 AUG 2026

YZSR344Y Date